



Photograph 21. Building 105 SAFR. Hazardous waste in small pieces (wood, metal, and plastic debris) placed in plastic bags then placed in Hazardous waste roll-off, September 2002.



Photograph 22. Building 105 SAFR. Typical scaffolding erected to allow access to elevated range areas, September 2002.



Photograph 23. Building 105 SAFR. Inside containment area; demolition of wood framing, September 2002.



Photograph 24. Building 105 SAFR. Narrow access drive east side of building, September 2002.



Photograph 17. Building 105 SAFR. Sewer sump in foreground; above at rear is ventilation window used to remove waste from basement, September 2002.



Photograph 18. Building 105 SAFR. Demolition worker in PPE, September 2002.